

SB100112, 115, 410 & 115+Horn Circuit Diagram

This applies to ALL models from ALL years

We do not have any instruction manuals... not even to scan/photocopy - sorry!

It is **not possible** to supply MosFet power transitors for the AX120P Power module. If you have ANY problems with this module, then check R9 (12k) is actually 12K. They can go high or open circuit! Replace it with a 2W resistor, as a matter of course, to prevent future failure!

> For dating information, please look inside the amplifier We do **not** hold serial number history





